



ADDENDUM #1

RFP # 18-020

RFP for Roof Repair at the Carrollton South Service Center and Roof Replacement at the Indian Creek Golf Course Club House

May 24, 2018

The following changes/clarifications have been made to the specifications:

1. The RFP due date and time has not changed, the RFP due date will remain **Thursday, May 31, 2018 @ 2:30 PM.**
2. **The following question was presented to the City of Carrollton:**
 - i. Question:
Would the city of Carrollton consider GAF a acceptable manufacture.
 - ii. Answer:
No
3. **Regarding Coating as mentioned in Section 6.0 Roofing Materials – Line 3.11**
 - i. The following additional coating manufacturer is acceptable to be used on the South Service Center repair:
 - ii. Karnak Corp. Karnak 404/505 Roof Coating System with a minimum 10 year mfg warranty.
4. **Referencing Section 6.0 Roofing Materials - Line 4.2**
 - i. Due to the site staging issues at the Indian Creek Golf Course Clubhouse, install a torch applied, 2 ply SBS modified bitumen roof system. No asphalt will be allowed.

*****THIS ADDENDUM SHOULD BE RETURNED WITH THE ORIGINAL RFP*****

PLEASE COMPLETE THE INFORMATION BELOW:

SIGNATURE _____ DATE _____

PRINTED NAME _____ TITLE _____

COMPANY _____

MAILING ADDRESS _____

PHONE NUMBER _____ FAX NUMBER _____ E-MAIL ADDRESS _____